



GRETCHEN WHITMER
GOVERNOR

STATE OF MICHIGAN
DEPARTMENT OF LICENSING AND REGULATORY AFFAIRS
LANSING

MARLON I. BROWN, DPA
DIRECTOR

February 26, 2026

Clifford Brown
Care Assistant Living Home Inc.
430 Franklin Lake Circle
Oxford, MI 48371

RE: License #: AS630301800
Care Assistant Living
31521 W. Stonewood Ct.
Farmington, MI 48334

Dear Clifford Brown:

Attached is the Renewal Licensing Study Report for the facility referenced above. You have submitted an acceptable written corrective action plan addressing the violations cited in the report. To verify your implementation and compliance with this corrective action plan:

- You are to submit documentation of compliance.
- You are to submit a Statement of Correction.

The study has determined substantial compliance with applicable licensing statutes and administrative rules. Therefore, your license is renewed. It is valid only at your present address and is nontransferable.

Please contact me with any questions. In the event that I am not available and you need to speak to someone immediately, you may contact the local office at (248) 972-9136.

Sincerely,

A handwritten signature in cursive script that reads "Frodet Dawisha". The signature is written in dark ink on a white background.

Frodet Dawisha, Licensing Consultant
Bureau of Community and Health Systems
3026 W. Grand Blvd., Ste 9-100
Cadillac Place
Detroit, MI 48202
(248) 303-6348

**MICHIGAN DEPARTMENT OF LICENSING AND REGULATORY AFFAIRS
BUREAU OF COMMUNITY AND HEALTH SYSTEMS
RENEWAL INSPECTION REPORT**

I. IDENTIFYING INFORMATION

License #:	AS630301800
Licensee Name:	Care Assistant Living Home Inc.
Licensee Address:	430 Franklin Lake Circle Oxford, MI 48371
Licensee Telephone #:	(248) 722-7171
Licensee/Licensee Designee:	Clifford Brown
Administrator:	Ebony Goree
Name of Facility:	Care Assistant Living
Facility Address:	31521 W. Stonewood Ct. Farmington, MI 48334
Facility Telephone #:	(248) 254-3195
Original Issuance Date:	08/18/2009
Capacity:	6
Program Type:	PHYSICALLY HANDICAPPED AGED ALZHEIMERS

II. METHODS OF INSPECTION

Date of On-site Inspection(s): 02/26/2026

Date of Bureau of Fire Services Inspection if applicable: N/A

Date of Health Authority Inspection if applicable: N/A

No. of staff interviewed and/or observed 1

No. of residents interviewed and/or observed 4

No. of others interviewed 2 Role: LD/Admin

- Medication pass / simulated pass observed? Yes No If no, explain.
 - Medication(s) and medication record(s) reviewed? Yes No If no, explain.
 - Resident funds and associated documents reviewed for at least one resident? Yes No If no, explain.
 - Meal preparation / service observed? Yes No If no, explain.
 - Fire drills reviewed? Yes No If no, explain.
 - Fire safety equipment and practices observed? Yes No If no, explain.
 - E-scores reviewed? (Special Certification Only) Yes No N/A
If no, explain.
 - Water temperatures checked? Yes No If no, explain.
 - Incident report follow-up? Yes No If no, explain.
 - Corrective action plan compliance verified? Yes CAP date/s and rule/s:
N/A
 - Number of excluded employees followed-up? N/A
 - Variances? Yes (please explain) No N/A
- Health Care Appraisal Form

III. DESCRIPTION OF FINDINGS & CONCLUSIONS

This facility was found to be in non-compliance with the following rules:

R 400.645	Environmental health.
	(3) A licensee shall provide hot and cold running water under pressure. A licensee shall maintain the hot water temperature for a resident's use at a range of 105 degrees Fahrenheit to 120 degrees Fahrenheit at the fixture.

During the on-site inspection on 02/26/2026, the hot water temperature was below the range of 105°-120° Fahrenheit in the kitchen (102.2°), in bathroom #1 (101.3°), and in bathroom #2 (103.8°).

R 400.647	Safety and maintenance of premises.
	(5) Floors, walls, and ceilings must be cleanable, maintained clean, and in good repair.

During the on-site inspection on 02/26/2026, the tile floor in the staff bathroom and the tile floor in the basement were broken. The wall in the laundry room above the door needed repair as there is a large crack.

R 400.715	Facility environment; fire safety, adoption by reference.
	(2) Instead of the interconnected multi-station smoke detection system being powered by the facility's electrical service, a wireless system in compliance with section 29.10.8.1 to 29.10.8.2.5 of the National Fire Protection Association (NFPA) 72, National Fire Alarm and Signaling Code, 2019 edition is accepted. The other requirements in subrule (1) of this rule still apply. NFPA 72, National Fire Alarm and Signaling Code, 2019 edition, is adopted by reference and available to purchase on the National Fire Protection Association website at https://www.nfpa.org at a cost of \$163.00 for nonmembers of the NFPA and \$146.70 for NFPA members at the time of adoption of these rules. A copy of NFPA 72 is available for inspection and distribution from the Bureau of Community and Health Services, Department of Licensing and Regulatory Affairs, 611 West Ottawa Street, P.O. Box 30664, Lansing, Michigan 48909 at a cost of 15 cents per page as of the time of the adoption of NFPA 72.

During the on-site inspection on 02/26/2026, the fire alarm was tested and not working properly.

R 400.721	Interior finishes prohibited materials.
	The following materials must not be used as an interior finish in a facility unless they are at least class C rated: (a) Asphalt paper. (b) Cork. (g) Other finish materials that contribute to the rapid spread of fire or give off dense smoke or toxic gases.

During the on-site inspection on 02/26/2026, the basement ceiling tiles were of cork material. The interior finish needs to be at least class C rated.

R 400.729	Heating equipment.
	(2) A furnace, water heater, heating appliances, pipes, wood-burning stoves and furnaces, and other flame- or heat-producing equipment must be installed in a fixed or permanent manner and in accordance with a manufacturer's instructions and maintained in a safe condition. Clothes dryers must be properly vented to the outside using permanent metal duct work.

During the on-site inspection on 02/26/2026, the dryer in the laundry room was not equipped with a metal duct.

R 400.739	Heating.
	(1) A facility shall be heated by an approved heating plant. If the heating plant is in the basement of the facility, standard building material is sufficient for the floor separation that must include at least 1 3/4-inch solid wood core door or equivalent to create a floor separation between the basement and the first floor. If the heating plant is on the same level as the residents, the furnace room must be separated from the remainder of the facility with materials that will afford a minimum 1 hour protected enclosure. A permanent outside vent that cannot be closed must be incorporated in the design of heating plant rooms so that adequate air for proper combustion is ensured.

During the on-site inspection on 02/26/2026, the furnace door in the basement was not closing properly.

A corrective action plan was requested and approved on 02/26/2026. It is expected that the corrective action plan be implemented within the specified time frames as outlined in the approved plan. A follow-up evaluation may be made to verify compliance. Should the corrections not be implemented in the specified time, it may be necessary to reevaluate the status of your license.

IV. RECOMMENDATION

An acceptable corrective action plan has been received. Renewal of the license is recommended.



02/26/2026

Frodet Dawisha
Licensing Consultant

Date