

GRETCHEN WHITMER
GOVERNOR

STATE OF MICHIGAN DEPARTMENT OF LICENSING AND REGULATORY AFFAIRS LANSING

ORLENE HAWKS DIRECTOR

November 4, 2021

Nicholas Burnett Flatrock Manor, Inc. 2360 Stonebridge Drive Flint, MI 48532

RE: License #: AS250406894

Lippincott

4408 Lippincott Blvd. Burton, MI 48519

Dear Mr. Burnett:

Attached is the Renewal Licensing Study Report for the facility referenced above. The violations cited in the report require the submission of a written corrective action plan. The corrective action plan is due 15 days from the date of this letter and must include the following:

- How compliance with each rule will be achieved.
- Who is directly responsible for implementing the corrective action for each violation.
- Specific dates for each violation as to when the correction will be completed or implemented.
- How continuing compliance will be maintained once compliance is achieved.
- The signature of the licensee or licensee designee or home for the aged authorized representative and a date.

Upon receipt of an acceptable corrective plan, a regular license will be issued. If you fail to submit an acceptable corrective action plan, disciplinary action will result.

Please contact me with any questions. In the event that I am not available and you need to speak to someone immediately, you may contact the local office at (517) 284-9730.

Sincerely,

Christina Garza, Licensing Consultant Bureau of Community and Health Systems 611 W. Ottawa Street P.O. Box 30664 Lansing, MI 48909 (810) 240-2478

MICHIGAN DEPARTMENT OF LICENSING AND REGULATORY AFFAIRS BUREAU OF COMMUNITY AND HEALTH SYSTEMS RENEWAL INSPECTION REPORT

I. IDENTIFYING INFORMATION

License #: AS250406894

Licensee Name: Flatrock Manor, Inc.

Licensee Address: 7012 River Road

Flushing, MI 48433

Licensee Telephone #: (810) 964-1430

Licensee/Licensee Designee: Nicholas Burnett

Administrator: Carrie Aldrich

Name of Facility: Lippincott

Facility Address: 4408 Lippincott Blvd.

Burton, MI 48519

Facility Telephone #: (810) 877-6932

Original Issuance Date: 04/21/2021

Capacity: 6

Program Type: PHYSICALLY HANDICAPPED

DEVELOPMENTALLY DISABLED

MENTALLY ILL

II. METHODS OF INSPECTION

Dat	e of On-site Inspection(s	09/20/2021	
Date of Bureau of Fire Services Inspection if applicable: N/A			N/A
Date of Health Authority Inspection if applicable:			01/14/2021
Inspection Type:		☐ Interview and Observation☐ Combination	⊠ Worksheet □ Full Fire Safety
No. of staff interviewed and/or observed No. of residents interviewed and/or observed No. of others interviewed N/A Role:		l and/or observed	3 5
•	Medication pass / simu	lated pass observed? Yes ⊠	No ☐ If no, explain.
•	Medication(s) and medication record(s) reviewed? Yes \boxtimes No \square If no, explain		
•	Resident funds and associated documents reviewed for at least one resident? Yes \boxtimes No \square If no, explain. Meal preparation / service observed? Yes \square No \boxtimes If no, explain. It was not meal time at time of inspection. Fire drills reviewed? Yes \boxtimes No \square If no, explain.		
•	Fire safety equipment and practices observed? Yes $igtimes$ No $igcup$ If no, explain.		
•	E-scores reviewed? (Special Certification Only) Yes No N/A In If no, explain. Water temperatures checked? Yes No If no, explain.		
•	Incident report follow-up? Yes ⊠ No □ If no, explain.		
•	Corrective action plan of N/A ⊠ Number of excluded en	compliance verified? Yes 🗌	CAP date/s and rule/s: N/A ⊠
•	Variances? Yes ⊠ (please explain) No □ N/A □ AS315(3)		

III. DESCRIPTION OF FINDINGS & CONCLUSIONS

This facility was found to be in non-compliance with the following rules:

R 400.14401 Environmental health.

(7) Each habitable room shall have direct outside ventilation by means of windows, louvers, air-conditioning, or mechanical ventilation. During fly season, from April to November, each door, openable window, or other opening to the outside that is used for ventilation purposes shall be supplied with a standard screen of not less than 16 mesh.

At time of inspection, resident bedroom windows were not supplied with a standard screen.

R 400.14408 Bedrooms generally.

(7) Bedrooms shall have at least 1 easily openable window.

At time of inspection, resident bedrooms did not have at least 1 easily operable window.

R 400.14505

Smoke detection equipment; location; battery replacement; testing, examination, and maintenance; spacing of detectors mounted on ceilings and walls; installation requirements for new construction, conversions and changes of category.

- (1) At least 1 single-station, battery-operated smoke detector shall be installed at the following locations:
- (a) Between the sleeping areas and the rest of the home. In homes that have more than 1 sleeping area, a smoke detector shall be installed to protect each separate sleeping area.
- (b) On each occupied floor, in the basement, and in areas of the home that contain flame- or heat-producing equipment.

At time of inspection, there was not at least 1 single-station, battery-operated some detector installed in areas of the home that contain flame- or heat-producing equipment (kitchen).

IV. RECOMMENDATION

Contingent upon receipt of an acceptable corrective action plan, renewal of the license is recommended.

11/4/2021

Date

Christina Garza

Licensing Consultant