



JENNIFER M. GRANHOLM
GOVERNOR

STATE OF MICHIGAN
FAMILY INDEPENDENCE AGENCY
OFFICE OF CHILDREN AND ADULT LICENSING



MARIANNE UDOW
DIRECTOR

June 28, 2004

Christine Hench
JARC
Suite 100
30301 Northwestern
Farmington Hills, MI 483343233

RE: License #: AS630016142
Katzman
5425 Pond Bluff Dr
West Bloomfield, MI 48323

Dear Ms. Hench:

Attached is the Addendum to the Original Licensing Study Report for the above referenced facility.

Please review the enclosed documentation for accuracy and feel free to contact me with any questions. In the event that I am not available and you need to speak to someone immediately, please feel free to contact the local office at (248) 975-5053.

Sincerely,

Sharon A. King, Licensing Consultant
Office of Children and Adult Licensing
Suite 358
41000 Woodward
Bloomfield Hills, MI 48304
(248) 975-5086

Enclosure

**MICHIGAN FAMILY INDEPENDENCE AGENCY
OFFICE OF CHILDREN AND ADULT LICENSING
ADDENDUM TO ORIGINAL LICENSING STUDY REPORT**

I. IDENTIFYING INFORMATION

License #: AS630016142

Licensee Name: JARC

Licensee Address: Suite 100
30301 Northwestern
Farmington Hills, MI 483343233

Licensee Telephone #: (248) 538-6611

Administrator/Licensee Designee: Christine Hench, Designee

Name of Facility: Katzman

Facility Address: 5425 Pond Bluff Dr
West Bloomfield, MI 48323

Facility Telephone #: (248) 682-9374

Capacity: 6

Program Type: CLF/DD
DEVELOPMENTALLY DISABLED

II. Purpose of Addendum

This is an addendum to the Licensing Study Report on the Katzman Home renewal inspection that was completed on 03/31/2004.

III. Methodology

06/25/2004 An on-site inspection was made to review need for smoke detectors in the laundry room, kitchen and kitchen dining area.

IV. Description of Findings and Conclusions

R 400.14505 **Smoke detection equipment; location; battery replacement; testing, examination, and maintenance; spacing of detectors mounted on ceilings and walls; installation requirements for new construction, conversions and changes of category.**

(1) At least 1 single-station, battery-operated smoke detector shall be installed at the following locations:

(a) Between the sleeping areas and the rest of the home. In homes that have more than 1 sleeping area, a smoke detector shall be installed to protect each separate sleeping area.

(b) On each occupied floor, in the basement, and in areas of the home that contain flame- or heat-producing equipment.

At the renewal inspection on 03/31/2004, no smoke detectors were found in the first-floor laundry room, between the kitchen and garage, and in the kitchen and the kitchen dining area.

On 06/25/2004, a follow-up on-site inspection was made to ascertain whether there was need for installation of smoke detectors in the laundry room, kitchen and kitchen dining area since heat detectors had already been installed at these locations. Since these locations were found to have small heads identified as heat detectors that comply with R 400.14505 (2), the installation of additional smoke detectors is not required at this time.

V. Recommendation

With receipt of an acceptable corrective action plan in response to the other violations cited in the Licensing Study Report dated 04/13/2004, it is recommended that a renewal license and special certification for the Developmentally Disabled be issued for this Adult Foster Care small group home facility with a capacity of six (6).

Sharon A. King
Licensing Consultant

Date