



RICK SNYDER
GOVERNOR

STATE OF MICHIGAN
DEPARTMENT OF LICENSING AND REGULATORY AFFAIRS
LANSING

SHELLY EDGERTON
DIRECTOR

March 2, 2018

Eric Van Acker
Willowbrook Rehab Services Inc
7200 Challis Road
Brighton, MI 48116

RE: License #: AS470255073
Odyssey Home
1911 Odyssey
Brighton, MI 48114

Dear Mr. Van Acker:

Attached is the Addendum to the Original Licensing Study Report for the above referenced facility.

Please review the enclosed documentation for accuracy and contact me with any questions. In the event that I am not available and you need to speak to someone immediately, please contact the local office at (313) 456-0380.

Sincerely,

A handwritten signature in cursive script, reading "Candace L. Pilarski".

Candace Pilarski, Licensing Consultant
Bureau of Community and Health Systems
611 W. Ottawa Street
P.O. Box 30664
Lansing, MI 48909
(517) 284-8967

enclosure

**MICHIGAN DEPARTMENT OF LICENSING AND REGULATORY AFFAIRS
BUREAU OF COMMUNITY AND HEALTH SYSTEMS
ADDENDUM TO ORIGINAL LICENSING STUDY REPORT**

I. IDENTIFYING INFORMATION

License #:	AS470255073
Licensee Name:	Willowbrook Rehab Services Inc
Licensee Address:	7200 Challis Road Brighton, MI 48116
Licensee Telephone #:	(810) 227-0119
Administrator/Licensee Designee:	Eric Van Acker, Designee
Name of Facility:	Odyssey Home
Facility Address:	1911 Odyssey Brighton, MI 48114
Facility Telephone #:	(810) 227-0119
Capacity:	6
Program Type:	TRAUMATICALLY BRAIN INJURED

II. Purpose of Addendum

This facility was licensed in 2005 with a winding staircase between the main and basement levels of the home. A safety evaluation summary of the staircase was not contained in the Original Licensing Study Report at the time the license was issued.

III. Description of Findings and Conclusions

The physical plant contains a winding staircase leading from the main level of the home to the lower basement level with approved resident bedrooms. There are 3 stairs that do not turn at landing but turn along with the winding direction of the stairs and are not uniform and consistent in size and direction. The licensee is responsible for assessing each resident at admission to ensure protection and safety related to their ability to navigate the winding staircase during regular use and in the case of emergency. The winding staircase is also equipped with a handrail that expands the entire length of the staircase to reinforce a safe passageway between the two levels. The licensee agrees to not admit residents to the lower level bedrooms who have impaired mobility, i.e. requiring regular use of a wheelchair, walker, or cane to ambulate or any other additional assistance from staff or other devices to ambulate and safely evacuate the home in the case of emergency.

IV. Recommendation

Any modifications to the winding staircase or failure of the licensee to continue with the aforementioned safety conditions, will result in further evaluation of the safety of the winding staircase and may require physical plant renovation.



Candace Pilarski
Licensing Consultant

3/2/2018
Date