

GRETCHEN WHITMER
GOVERNOR

STATE OF MICHIGAN DEPARTMENT OF LICENSING AND REGULATORY AFFAIRS LANSING

MARLON I. BROWN, DPA DIRECTOR

December 13, 2024

Dennis Strode Strode Adult Foster Care Inc. 5011 West Willow Highway Lansing, MI 48917

RE: License #: AS230382143

Strode Adult Foster Care Inc. 5011 West Willow Hwy. Lansing, MI 48917

Dear Mr. Strode:

Attached is the Addendum to the Original Licensing Study Report for the above referenced facility.

Please review the enclosed documentation for accuracy and contact me with any questions. In the event that I am not available and you need to speak to someone immediately, please contact the local office at (517) 284-9730.

Sincerely,

Jana Lipps, Licensing Consultant

Bureau of Community and Health Systems

611 W. Ottawa Street

P.O. Box 30664

Lansing, MI 48909

enclosure

MICHIGAN DEPARTMENT OF LICENSING AND REGULATORY AFFAIRS BUREAU OF COMMUNITY AND HEALTH SYSTEMS ADDENDUM TO ORIGINAL LICENSING STUDY REPORT

I. IDENTIFYING INFORMATION

License #: AS230382143

Licensee Name: Strode Adult Foster Care Inc.

Licensee Address: 5011 West Willow Highway

Lansing, MI 48917

Licensee Telephone #: (517) 881-1811

Administrator/Licensee Designee: Dennis Strode, Designee

Name of Facility: Strode Adult Foster Care Inc.

Facility Address: 5011 West Willow Hwy.

Lansing, MI 48917

Facility Telephone #: (517) 977-1243

Capacity: 6

Program Type: DEVELOPMENTALLY DISABLED

MENTALLY ILL

AGED

II. Purpose of Addendum

To modify and correct information from the original licensing study report, dated 7/5/16. To update the license to note that this facility is not wheelchair accessible and modify the population types served noted in the original licensing study report as Physically Handicapped, Aged, & Mentally III, to Developmentally Disabled, Aged, & Mentally III.

III. Methodology

On 12/10/24 I conducted a regular renewal inspection at the facility. I observed that the facility did not have two means of egress equipped with wheelchair ramps. The back exit has a step down and does not have a path on solid unobstructed ground which would allow a wheelchair occupant to move a safe distance away from the building. This exit terminates on a cement slab which leads to grass. There is no path that would be easily traversed in the winter months to move the wheelchair occupant a safe distance away from the building in the event of a fire. Furthermore, the facility has a step down, from the kitchen to the back hallway where there are four resident bedrooms. A wheelchair occupant would not be able to get from the kitchen to this back hallway due to this step.

On 12/13/24 I observed that the Original Licensing Study Report dated 7/5/16, identifies that the facility is wheelchair accessible. I also observed in this report that the population type noted to be served is Physically Handicapped, Aged, & Mentally III. I further observed the population types noted to be served in the BITs system were, Developmentally Disabled, Mentally III, & Aged.

IV. Description of Findings and Conclusions

Based upon observations made during the on-site inspection on 12/10/24, it can be determined that the original licensing study report, dated 7/5/16, incorrectly identified this facility as wheelchair accessible. This report also incorrectly identified Physically Handicapped as a population type being served. This modification report serves to correct these errors and change the population type of Physically Handicapped, and add Developmentally Disabled. Also, the facility will now be noted as not being wheelchair accessible as there are not ramps at both exits, unobstructed pathways inside the facility, and no safe solid pathway away from the back exit that can be easily traversed by wheelchair occupants.

Recommendation ٧.

Modify the license to add Developmentally Disabled as a population type served, delete Physically Handicapped as a population type served, and correct the wheelchair accessibility status to, not wheelchair accessible.

Jana Lipps Date

Licensing Consultant

Approved:

12/13/2024 Date

Dawn Timm

Area Manager