

GRETCHEN WHITMER
GOVERNOR

STATE OF MICHIGAN DEPARTMENT OF LICENSING AND REGULATORY AFFAIRS LANSING

MARLON I. BROWN, DPA DIRECTOR

June 12, 2025

Anna Hinton Pioneer Resources 1145 Wesley Ave. Muskegon, MI 49442

RE: License #:	AS610016251
	Ruddiman Home
	224 Ruddiman
	North Muskegon, MI 49445

Dear Ms. Hinton:

Attached is the Renewal Licensing Study Report for the facility referenced above. The violations cited in the report require the submission of a written corrective action plan. The corrective action plan is due 15 days from the date of this letter and must include the following:

- How compliance with each rule will be achieved.
- Who is directly responsible for implementing the corrective action for each violation.
- Specific dates for each violation as to when the correction will be completed or implemented.
- How continuing compliance will be maintained once compliance is achieved.
- The signature of the licensee or licensee designee or home for the aged authorized representative and a date.

Upon receipt of an acceptable corrective plan, a regular license and special certification will be issued. If you fail to submit an acceptable corrective action plan, disciplinary action will result.

Please contact me with any questions. If I am not available and you need to speak to someone immediately, you may contact the local office at (616) 356-0100.

Sincerely, Elizabeth Ellicott

Elizabeth Elliott, Licensing Consultant Bureau of Community and Health Systems 350 Ottawa, N.W. Grand Rapids, MI 49503 (616) 901-0585

MICHIGAN DEPARTMENT OF LICENSING AND REGULATORY AFFAIRS BUREAU OF COMMUNITY AND HEALTH SYSTEMS RENEWAL INSPECTION REPORT

I. IDENTIFYING INFORMATION

License #:	AS610016251			
Licensee Name:	Pioneer Resources			
Licensee Address:	1145 Wesley Ave.			
	Muskegon, MI 49442			
Licensee Telephone #:	(231) 773-5355			
	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			
Licensee/Licensee Designee:	Anna Hinton, Designee			
Administrator	Appa Hinton Administrator			
Administrator:	Anna Hinton, Administrator			
Name of Facility:	Ruddiman Home			
Name of Facility.	Nudulilaii i loille			
Facility Address:	224 Ruddiman			
Tuomity Additions.	North Muskegon, MI 49445			
	Trotal Macrogen, IIII 10 110			
Facility Telephone #:	(231) 744-6362			
, , , , , , , , , , , , , , , , , , ,				
Original Issuance Date:	12/15/1994			
Capacity:	6			
-				
Program Type:	DEVELOPMENTALLY DISABLED			
	ALZHEIMERS			

II. METHODS OF INSPECTION

Date	e of On-site Inspection(s):	06/10/2	025	
Date	e of Bureau of Fire Services Inspection if appl	icable:	N/A	
Date	e of Environmental/Health Inspection if applica	able: 06	/10/2025	
No.	of staff interviewed and/or observed of residents interviewed and/or observed of others interviewed 2 Role: A. Hintor	n, LD-L.	3 4 Robinson, mgr	
•	Medication pass / simulated pass observed? At the time of the inspection, resident medical administration. A review of resident medication Medication(s) and medication record(s) review	ations we ons and	ere not due for the MAR was conducted.	
•	Resident funds and associated documents reviewed for at least one resident? Yes \boxtimes No \square If no, explain. Meal preparation / service observed? Yes \boxtimes No \square If no, explain.			
•	Fire drills reviewed? Yes ⊠ No ☐ If no, ex	cplain.		
•	Fire safety equipment and practices observe	d? Yes	⊠ No If no, explain.	
•	E-scores reviewed? (Special Certification On If no, explain. Water temperatures checked? Yes ⊠ No □	•		
•	Incident report follow-up? Yes ⊠ No ☐ If i	no, expla	ain.	
•	Corrective action plan compliance verified? `N/A ⊠	Yes 🗌	CAP date/s and rule/s:	
•	Number of excluded employees followed-up?	?	N/A ⊠	
	Variances? Ves (nlease explain) No	N/A 🔀		

III. DESCRIPTION OF FINDINGS & CONCLUSIONS

This facility was found to be in non-compliance with the following rules:		
R 400.14507 Means of egress generally.		
	(5) A door that forms a part of a required means of egress shall be not less than 30 inches wide and shall be equipped with positive-latching, non-locking-against-egress hardware.	

Finding: All of the doors that exit the facility are not non-locking-against-egress. The two doors that form a part of a required means of egress are not equipped with the proper hardware that unlock and open with the twist of the doorknob.

Licensee Response: Anna Hinton, LD and Administrator & LaQuandra Robinson, home manager stated they will have the doors fixed immediately.

On 06/10/2025, I conducted an exit conference with Ms. Hinton, Licensee Designee after the inspection was completed. Ms. Hinton stated she has no idea when the hardware was changed but they always used to meet the licensing requirements. Ms. Hinton stated she will have a maintenance order placed immediately to get different, non-locking against egress hardware installed on the doors to the outside.

IV. RECOMMENDATION

Contingent upon receipt of an acceptable corrective action plan, renewal of the license is recommended.

Climbet Client

06/12/2025

Elizabeth Elliott

Licensing Consultant