



GRETCHEN WHITMER
GOVERNOR

STATE OF MICHIGAN
DEPARTMENT OF LICENSING AND REGULATORY AFFAIRS
LANSING

MARLON I. BROWN, DPA
ACTING DIRECTOR

October 12, 2023

Tyler Curtis
CBI Rehabilitation Services, Inc.
3446 E. Lake Lansing Rd.
East Lansing, MI 48823

RE: License #: AS330337346
Belmonte Circle
606 Belmonte Circle
East Lansing, MI 48823

Dear Mr. Curtis:

Attached is the Addendum to the Original Licensing Study Report for the above referenced facility.

Please review the enclosed documentation for accuracy and contact me with any questions. In the event that I am not available and you need to speak to someone immediately, please contact the local office at (517) 284-9730.

Sincerely,

A handwritten signature in cursive script that reads "Jana Lipps".

Jana Lipps, Licensing Consultant
Bureau of Community and Health Systems
611 W. Ottawa Street
P.O. Box 30664
Lansing, MI 48909

enclosure

**MICHIGAN DEPARTMENT OF LICENSING AND REGULATORY AFFAIRS
BUREAU OF COMMUNITY AND HEALTH SYSTEMS
ADDENDUM TO ORIGINAL LICENSING STUDY REPORT**

I. IDENTIFYING INFORMATION

License #:	AS330337346
Licensee Name:	CBI Rehabilitation Services, Inc.
Licensee Address:	3446 E. Lake Lansing Rd. East Lansing, MI 48823
Licensee Telephone #:	(517) 349-6975
Administrator/Licensee Designee:	Tyler Curtis, Designee
Name of Facility:	Belmonte Circle
Facility Address:	606 Belmonte Circle East Lansing, MI 48823
Facility Telephone #:	(517) 349-6975
Capacity:	6
Program Type:	DEVELOPMENTALLY DISABLED MENTALLY ILL TRAUMATICALLY BRAIN INJURED

II. Purpose of Addendum

Licensee Designee, Tyler Curtis, has made a verbal request to modify the terms of the existing license to add wheelchair accessibility.

III. Methodology

An AFC licensing renewal inspection was completed at the facility on 8/22/23. I observed that the facility has two separate forms of egress that can accommodate residents who utilize wheelchairs. Both exits have a clear path which lead a safe distance away from the building in the event of a fire. The facility was also found to have doorways that measured at least 30 inches wide for exits, resident bedrooms, and bathrooms. The facility also has one completely handicap accessible shower room for use by residents who require a wheelchair.

IV. Description of Findings and Conclusions

After completion of the on-site renewal inspection, it can be determined that the facility meets the requirements for wheelchair accessibility by having adequate means of egress, sufficient accommodations for personal hygiene, and doorways that are wide enough to accommodate a wheelchair.

V. Recommendation

The license shall be updated to include the provision for wheelchair accessibility.



09/18/23

Jana Lipps
Licensing Consultant

Date

Approved:



10/12/2023

Dawn Timm
Area Manager

Date